

I-45 Bridge Project Cypress Creek Clean Out



Updated
4/12/23

Photos from 3/30/23

Riprap being laid under the south bank side of the creek.



From the north side of the creek looking at work being done on the south bank under the North side of I45.





New Drainage
Outfall on
South side of
creek



Riprap being
laid under the
south bank
side of the
creek.




Photos from 3/30/23





WCID Board
Member Vanessa
Sommer, District
Engineer John
Davis meeting
with TXDot
Officials



Cypress Creek
flowing east
under I-45



Photos from 3/30/23



Photos from 3/30/23

TXDot explaining next steps in clearing debris from under north side of creek under I-45.

Photos from 3/30/23

Underneath
northbound
side of I-45
on north
bank.





Taken after the significant rain event in January 2023 – facing south bank



Photos from 3/30/23



Taken 4.11.23 under
north side of bridge.



Photos from
4/11/23





Taken 4.11.23 under
north side of bridge.



Photos from
4/11/23

